• No judgment is made about why the scan failed, it could be an that an inspector was just trying to get the chip to read, or any other of another of a number of reasons.

Observations:

In most cases the MRZ scanned in from the passport data page and the one read in from the chip were not equal. From a software perspective this makes it extremely difficult to identify if there is a problem with the data page or chip or both. Also, if this occurs often and the software alerts the inspector to the problem and it turns out not to be a problem the inspector may pay less attention to the mismatch warnings.

Results

Chip Reads

Chip Reads	Successful	liotal Attempts	% Successful
Unit A	124	401	31%
Unit Brown	188	324	58%
Unite	143	330	43%

Data Page/MRZ Scans

Data Rage/MRVA Scans	Successful)	Total Aftemps:	% डिगल्डर्झाम
UnitA	313	532	59%
Unit B	327	383	85%
Unite	312	352	89%

Conclusions

